COMPLETION REPORT

1	Name of Work	: UGD Maintanance at Kirloskar Layout, NMH Layout & Sahyadri layout in Bagalagunte Ward No.14
2	Estimated Amount	: 10.00 Lakhs
3	Head of Acount which is chargeable	: P-1771
4	Entrusment order No & Date	: :EE/DD/WO/436/2019-20 Date:24.10.2019
5	Name of Contractor	: Sri Basavalingaraju M.G
6	Time stipulated for completion of work	: 90 Days
7	Measurement recorded in	: MB No: 4884 : Page No: 48831 to 48832
8	Check measurement of the Asst. Exe.Engineer Executive Engineer on	: BR No: : Page No:
9	Name of the Office/ Office in charge of the Work	:
10	(a) Asst. Engineer/Jn. Engineer (b) Asst. Executive Engineer	: Venkatesappa : Ranganatha
11	Work Completed Date	: 08.09.2021

Sanctioned Estimate Amount		Amount Claims as per actually vide as per Bills
	DIFFERENCE	
EXCESS		SAVING
Rs. -	Rs. -	890=00

1. Certified that the above work has been completed within stipulated time noted in the work Order/
2. Certified that the above work has been executed by the contractors satisfactorily in accordence with the specfn as embodied in the agreement.

ASST.ENGINEER

ASST EXECUTIVE ENGINEER
BBMP

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರ
ಜ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಜ.ಜ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

ACCOUNT SUPTD ( )

EXECUTIVE ENGINEER

Scanned with CamScanner